# UNITED STATES DISTRICT COURT SOUTHERN DISTRICT OF FLORIDA

DANIEL LOPEZ, Plaintiff, vs.

CORSELY INVESTMENT, INC. and LES ARTISTES, INC,
Defendants.

### **COMPLAINT**

Plaintiff, DANIEL LOPEZ (hereinafter "Plaintiff"), by his undersigned, hereby files this Complaint and sues Defendants, CORSELY INVESTMENT, INC. and LES ARTISTES, INC (hereinafter "Defendants"), for injunctive relief pursuant to the Americans with Disabilities Act, 42 U.S.C. § 12181, *et seq.*, (hereinafter the "A.D.A"), the ADA's Accessibility Guidelines, 28 C.F.R. Part 36 (hereinafter the "ADAAG"), and the Florida Building Code.

#### **JURISDICTION & VENUE**

- 1. This Court has original jurisdiction over the action pursuant to 28 U.S.C., §§1331 and 1343 for Plaintiff's claims arising under 42 U.S.C. § 12181. *et seq.*, based upon Defendants' violations of Title III of the ADA (see also, 28 U.S.C. §§ 2201 and 2202).
- 2. The subject property is a cafe located on or about 311 Johnson St, Hollywood, FL 33019 (hereinafter "Subject Premises").
- 3. All events giving rise to this lawsuit occurred in the State of Florida. Venue is proper in this Court as the premises are located in the Southern District.

#### **PARTIES**

1. Plaintiff, DANIEL LOPEZ, is a resident of Miami, Florida, and is *sui juris*. He is a qualified individual with disabilities under the ADA law. In 2008 Daniel became a bilateral

amputee, above the knee, due to surgery. He is bound to ambulate in a wheelchair. His access to the facility and/or full and equal enjoyment of the goods, services, facilities, privileges, advantages, and/or accommodations offered therein was denied and/or limited because of these disabilities, and will be denied and/or limited in the future unless and until Defendant is compelled to remove the physical barriers to access and ADA violations which exist at the facility, including but not limited, to those set forth in the Complaint.

- **4.** Defendant, CORSELY INVESTMENT, INC., is a corporation which is authorized to and does transact business in the State of Florida and within this judicial district.
- 5. Pursuant to the Miami-Dade Property Appraiser's Office, Defendant, CORSELY INVESTMENT, INC., is the owner and/or operator/manager of the real property located on or 311 Johnson St, Hollywood, FL 33019 (hereinafter the "Subject Premises"). This is the building where the Subject Premises is located.
- **6.** Defendant, LES ARTISTES, INC, is a corporation which is authorized to and does transact business in the State of Florida and within this judicial district.
- 7. According to the Florida Department of Business and Professional Regulation, the Defendant, LES ARTISTES, INC, was licensed on May 13, 2020 to provide Permanent Food Service and Seating and occupies 311 Johnson St, Hollywood, FL 33019 as a cafe known as "CAFÉ CLUB".
- **8.** The Subject Premises is owned and/or operated by the Defendants and is a public accommodation required by law to comply with the ADA and ADAAG.

#### FACTUAL ALLEGATIONS AND CLAIM

- **9.** Plaintiff visited the Subject Premises to dine and accessed to the extent possible, or attempted to access the Subject Premises and specific areas of the Subject Premises as described herein.
- 10. While visiting the Subject Premises, Plaintiff personally encountered or observed several barriers to access in violation of the ADA and ADAAG as detailed further herein at Paragraph 14. As a result, Plaintiff has been denied access to the Subject Premises and full and equal enjoyment of the goods and services offered therein because of his disability and will continue to be denied such access as a result of those barriers.
- 11. Said barriers to access at the Subject Premises endanger the safety of Plaintiff and all other individuals with disabilities, deny Plaintiff and others with disabilities equal access to the Subject Premises as to that of able-bodied persons, and causes social embarrassment due to the difficulties encountering such barriers to access—a social embarrassment that would not occur if the Subject Premises was in compliance with the ADA and ADAAG.
- 12. In encountering the barriers to access at the Subject Premises, and suffering the resulting discrimination, endangerment, and embarrassment—the Plaintiff sustained a lawful injury-in-fact pursuant to the ADA.
- 13. Pursuant to the mandates of 42 U.S.C. §12134(a), on September 15, 2010, the Department of Justice, Office of the Attorney General, published revised regulations for Title III of the Americans with Disabilities Act of 1990 in the Federal Register to implement the requirements of the ADA. Public accommodations were required to conform to these regulations on or before March 15, 2012.<sup>1</sup>

<sup>&</sup>lt;sup>1</sup> "Safe Harbor. Elements that have not been altered in existing facilities on or after March 15, 2012, and that comply with the corresponding technical and scoping specification for those elements in the 1991 Standards are not required to be modified in order to comply with the requirements set forth in the 2010 Standards" 28 CFR §36.304(d)(2)(i), however, the violations described herein violate both the 1991 Standards as well as the 2010 Standards.

- **14.** A specific, although not exclusive, list of unlawful physical barriers, dangerous conditions and ADA violations which preclude and/or limit Plaintiff's ability (because of his disability) to access the Facility and/or full and equal enjoyment of the goods, services, facilities, privileges, advantages and/or accommodations of the Facility include:
  - 1. Inaccessible entrance.
  - 2. Accessible route to establishment not provided as required.
  - 3. Accessible means of egress not provided as required.
  - 4. Raised floor surface at entrance door acts as a barrier to accessibility.
  - 5. Required ramp not provided for raised floor surface at entrance door.

ADAAG 206 Accessible Routes ADAAG 206.1 General.

Accessible routes shall be provided in accordance with 206 and shall comply with Chapter 4.

ADAAG 206.2 Where Required.

Accessible routes shall be provided where required by 206.2.

ADAAG 206.2.1 Site Arrival Points.

At least one accessible route shall be provided within the site from accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public transportation stops to the accessible building or facility entrance they serve.

ADAAG 206.4 Entrances.

Entrances shall be provided in accordance with 206.4. Entrance doors, doorways, and gates shall comply with 404 and shall be on an accessible route complying with 402.

ADAAG 207 Accessible Means of Egress ADAAG 207.1 General.

Means of egress shall comply with section 1003.2.13 of the International Building Code (2000 edition and 2001 Supplement) or section 1007 of the International Building Code (2003 edition) (incorporated by reference, "Referenced Standards" in Chapter 1).

ADAAG 402 Accessible Routes ADAAG 402.1 General.

Accessible routes shall comply with 402.

ADAAG 402.2 Components.

Accessible routes shall consist of one or more of the following components: walking surfaces with a running slope not steeper than 1:20, doorways, ramps, curb ramps excluding the flared sides, elevators, and platform lifts. All components of an accessible route shall comply with the applicable requirements of Chapter 4.

ADAAG 403 Walking Surfaces ADAAG 403.4 Changes in Level. Changes in level shall comply with 303

ADAAG 303.4 Ramps.

Changes in level greater than ½ inch high shall be ramped, and shall comply with 405 or 406.

- 6. Required minimum maneuvering clearance not provided at entrance door.
- 7. Non-compliant change in floor level within required maneuvering clearance at entrance door.

ADAAG 206 Accessible Routes ADAAG 206.1 General.

Accessible routes shall be provided in accordance with 206 and shall comply with Chapter 4.

ADAAG 206.2 Where Required.

Accessible routes shall be provided where required by 206.2.

ADAAG 206.2.1 Site Arrival Points.

At least one accessible route shall be provided within the site from accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public transportation stops to the accessible building or facility entrance they serve.

ADAAG 206.4 Entrances.

Entrances shall be provided in accordance with 206.4. Entrance doors, doorways, and gates shall comply with 404 and shall be on an accessible route complying with 402.

ADAAG 206.4.1 Public Entrances.

In addition to entrances required by 206.4.2 through 206.4.9, at least 60 percent of all public entrances shall comply with 404.

ADAAG 207 Accessible Means of Egress ADAAG 207.1 General.

Means of egress shall comply with section 1003.2.13 of the International Building Code (2000 edition and 2001 Supplement) or section 1007 of the International Building Code (2003 edition) (incorporated by reference, "Referenced Standards" in Chapter 1)

ADAAG 404.2.4 Maneuvering Clearances.

Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.

Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.

ADAAG 404.2.4.4 Floor or Ground Surface.

Floor or ground surface within required maneuvering clearances shall comply with 302. Changes in level are not permitted.

- 8. Inaccessible dining tables located at exterior dining area.
- 9. Required minimum knee and toe clearance not provided at dining tables located at exterior dining area.
- 10. A minimum percentage of existing dining tables required to be accessible not provided at exterior dining area.

ADAAG 226 Dining Surfaces and Work Surfaces ADAAG 226.1 General.

Where dining surfaces are provided for the consumption of food or drink, at least 5 percent of the seating spaces and standing spaces at the dining surfaces shall comply with 902.

ADAAG 902 Dining Surfaces and Work Surfaces ADAAG 902.1 General.

Dining surfaces and work surfaces shall comply with 902.2 and 902.3.

ADAAG 902.2 Clear Floor or Ground Space.

A clear floor space complying with 305 positioned for a forward approach shall be provided. Knee and toe clearance complying with 306 shall be provided.

ADAAG 306.2 Toe Clearance.

ADAAG 306.2.3 Minimum Required Depth.

Where toe clearance is required at an element as part of a clear floor space, the toe clearance shall extend 17 inches (430 mm) minimum under the element.

ADAAG 306.2.5 Width.

Toe clearance shall be 30 inches (760 mm) wide minimum.

ADAAG 306.3 Knee Clearance.

ADAAG 306.3.3 Minimum Required Depth.

Where knee clearance is required under an element as part of a clear floor space, the knee clearance shall be 11 inches deep minimum at 9 inches above the ground, and 8 inches deep minimum at 27 inches (685 mm) above the finish floor or ground.

ADAAG 306.3.5 Width.

Knee clearance shall be 30 inches (760 mm) wide minimum.

- 11. Inaccessible dining tables located at interior dining area.
- 12. Required minimum toe clearance not provided at dining tables located at interior dining area.
- 13. A minimum percentage of existing dining tables required to be accessible not provided at interior dining area.

ADAAG 226 Dining Surfaces and Work Surfaces ADAAG 226.1 General.

Where dining surfaces are provided for the consumption of food or drink, at least 5 percent of the seating spaces and standing spaces at the dining surfaces shall comply with 902.

ADAAG 902 Dining Surfaces and Work Surfaces ADAAG 902.1 General.

Dining surfaces and work surfaces shall comply with 902.2 and 902.3.

ADAAG 902.2 Clear Floor or Ground Space.

A clear floor space complying with 305 positioned for a forward approach shall be provided. Knee and toe clearance complying with 306 shall be provided.

ADAAG 306.2 Toe Clearance.

ADAAG 306.2.3 Minimum Required Depth.

Where toe clearance is required at an element as part of a clear floor space, the toe clearance shall extend 17 inches (430 mm) minimum under the element.

ADAAG 306.2.5 Width.

Toe clearance shall be 30 inches (760 mm) wide minimum.

- 14. Inaccessible seating benches located at interior dining area.
- 15. Seating benches located at interior dining area are not affixed to a wall as required.
- 16. Required back support not provided at seating benches located at interior dining area.

ADAAG 903 Benches ADAAG 903.1 General.

Benches shall comply with 903.

ADAAG 903.4 Back Support.

The bench shall provide for back support or shall be affixed to a wall. Back support shall be 42 inches (1065 mm) long minimum and shall extend from a point 2 inches (51 mm) maximum above the seat surface to a point 18 inches (455 mm) minimum above the seat surface. Back support shall be  $2\frac{1}{2}$  inches (64 mm) maximum from the rear edge of the seat measured horizontally.

- 17. Inaccessible service counter.
- 18. Non-compliant height of service counter exceeds maximum height allowance.

ADAAG227 Sales and Service ADAAG 227.1 General.

Where provided, check-out aisles, sales counters, service counters, food service lines, queues, and waiting lines shall comply with 227 and 904.

ADAAG 904.4 Sales and Service Counters.

Sales counters and service counters shall comply with 904.4.1 or 904.4.2.

The accessible portion of the counter top shall extend the same depth as the sales or service counter top.

ADAAG 904.4.1 Parallel Approach.

A portion of the counter surface that is 36 inches (915 mm) long minimum

and 36 inches (915 mm) high maximum above the finish floor shall be provided.

A clear floor or ground space complying with 305 shall be positioned for a parallel approach adjacent to the 36 inch (915 mm) minimum length of counter.

- 19. Accessible route to restroom not provided as required.
- 20. Required minimum maneuvering clearance not provided in corridor at exterior side of restroom door.

ADAAG 206 Accessible Routes ADAAG 206.1 General.

Accessible routes shall be provided in accordance with 206 and shall comply with Chapter 4.

ADAAG 206.2.4 Spaces and Elements.

At least one accessible route shall connect accessible building or facility entrances with all accessible spaces and elements within the building or facility which are otherwise connected by a circulation path unless exempted by 206.2.3 Exceptions 1 through 7.

ADAAG 402 Accessible Routes ADAAG 402.1 General.

Accessible routes shall comply with 402.

ADAAG 402.2 Components.

Accessible routes shall consist of one or more of the following components: walking surfaces with a running slope not steeper than 1:20, doorways, ramps, curb ramps excluding the flared sides, elevators, and platform lifts. All components of an accessible route shall comply with the applicable requirements of Chapter 4.

ADAAG 404.2.4 Maneuvering Clearances.

Minimum maneuvering clearances at doors and gates shall comply with 404.2.4.

Maneuvering clearances shall extend the full width of the doorway and the required latch side or hinge side clearance.

21. Non-compliant door knob at restroom door requires twisting of the wrist.

ADAAG 404 Doors, Doorways, and Gates ADAAG 404.1 General.

Doors, doorways, and gates that are part of an accessible route shall comply with 404.

ADAAG 404.2.7 Door and Gate Hardware.

Handles, pulls, latches, locks, and other operable parts on doors and gates shall comply with 309.4 Operable parts of such hardware shall be 34 inches (865 mm) minimum and 48 inches (1220 mm) maximum above the finish floor or ground.

ADAAG 309.4 Operation.

Operable parts shall be operable with one hand and shall not require tight grasping, pinching,

or twisting of the wrist. The force required to activate operable parts shall be 5 pounds maximum.

22. Non-compliant distance of water closet from side wall in restroom acts as a barrier to accessibility.

ADAAG 604 Water Closets and Toilet Compartments.

ADAAG 604.2 Location.

The water closet shall be positioned with a wall or partition to the rear and to one side.

The centerline of the water closet shall be 16 inches minimum to 18 inches maximum from the side wall or partition

- 23. Inaccessible hand soap dispenser in restroom.
- 24. Non-compliant mounted height of hand soap dispenser in restroom exceeds maximum height allowance.

ADAAG Advisory 606.1 General.

If soap and towel dispensers are provided, they must be located within the reach ranges specified in 308.

ADAAG 308.2 Forward Reach. ADAAG 308.2.1 Unobstructed.

Where a forward reach is unobstructed, the high forward reach shall be

48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.

ADAAG 308.2.2 Obstructed High Reach.

Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches maximum where the reach depth is 20 inches maximum. Where the reach depth exceeds 20 inches, the high forward reach shall be 44 inches maximum and the reach depth shall be 25 inches maximum.

ADAAG 308.3 Side Reach. ADAAG 308.3.1 Unobstructed.

Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be

15 inches minimum above the finish floor or ground.

ADAAG 308.3.2 Obstructed High Reach.

Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches maximum and the depth of the obstruction shall be 24 inches maximum. The high side reach shall be 48 inches maximum for a reach depth of 10 inches maximum. Where the reach depth exceeds 10 inches, the high side reach shall be 46 inches maximum for a reach depth of 24 inches maximum.

- 25. The first of two paper towel dispensers in restroom is inaccessible.
- 26. Non-compliant mounted height of the first of two paper towel dispensers in restroom exceeds maximum height allowance.

ADAAG Advisory 606.1 General.

If soap and towel dispensers are provided, they must be located within the reach ranges specified In 308. Locate soap and towel dispensers so that they are conveniently usable by a person at the accessible lavatory.

ADAAG 308.2 Forward Reach. ADAAG 308.2.1 Unobstructed.

Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.

ADAAG 308.2.2 Obstructed High Reach.

Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches maximum where the reach depth is 20 inches maximum. Where the reach depth exceeds 20 inches, the high forward reach shall be 44 inches maximum and the reach depth shall be 25 inches maximum.

ADAAG 308.3 Side Reach. ADAAG 308.3.1 Unobstructed.

Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be

48 inches maximum and the low side reach shall be 15 inches minimum above the finish floor or ground.

ADAAG 308.3.2 Obstructed High Reach.

Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches maximum and the depth of the obstruction shall be 24 inches maximum. The high side reach shall be 48 inches maximum for a reach depth of 10 inches maximum. Where the reach depth exceeds 10 inches, the high side reach shall be 46 inches maximum for a reach depth of 24 inches maximum.

- 27. The second of two paper towel dispensers in restroom is inaccessible.
- 28. Non-compliant mounted height of the second of two paper towel dispensers in restroom exceeds maximum height allowance.

ADAAG Advisory 606.1 General.

If soap and towel dispensers are provided, they must be located within the reach ranges specified In 308. Locate soap and towel dispensers so that they are conveniently usable by a person at the accessible lavatory.

ADAAG 308.2 Forward Reach. ADAAG 308.2.1 Unobstructed.

Where a forward reach is unobstructed, the high forward reach shall be 48 inches maximum and the low forward reach shall be 15 inches minimum above the finish floor or ground.

ADAAG 308.2.2 Obstructed High Reach.

Where a high forward reach is over an obstruction, the clear floor space shall extend beneath the element for a distance not less than the required reach depth over the obstruction. The high forward reach shall be 48 inches maximum where the reach depth is 20 inches maximum. Where the reach depth exceeds 20 inches, the high forward reach shall be 44 inches maximum and the reach depth shall be 25 inches maximum.

ADAAG 308.3 Side Reach. ADAAG 308.3.1 Unobstructed.

Where a clear floor or ground space allows a parallel approach to an element and the side reach is unobstructed, the high side reach shall be 48 inches maximum and the low side reach shall be

15 inches minimum above the finish floor or ground.

ADAAG 308.3.2 Obstructed High Reach.

Where a clear floor or ground space allows a parallel approach to an element and the high side reach is over an obstruction, the height of the obstruction shall be 34 inches maximum and the depth of the obstruction shall be 24 inches maximum. The high side reach shall be 48 inches maximum for a reach depth of 10 inches maximum. Where the reach depth exceeds 10 inches, the high side reach shall be 46 inches maximum for a reach depth of 24 inches maximum.

- 15. The above listing is not to be considered all-inclusive of the barriers, conditions or violations encountered by Plaintiff and/or which exist at the Facility. Plaintiff requires an inspection of the Facility in order to photograph, measure and determine all of the discriminatory acts violating the ADA.
- 16. The removal of the physical barriers, dangerous conditions and ADA violations set forth herein is readily achievable and can be accomplished and carried out without much difficulty or expense pursuant to 42 U.S.C. § 12182(B)(2)(A)(iv); 42 U.S.C. § 12181(9); and 28 C.F.R, § 36.304.
- 17. The ADA defines "readily achievable as "easily accomplishable and without much difficult or expenses." 42 U.S.C. §12181(9) Congress included in the ADA factors to be considered in evaluating whether removal of a barrier is "readily achievable." These factors are (1) nature and cost of the action; (2) overall financial resources of the facility or facilities involved; (3) number of persons employed at such facility; (4) effect on expenses and resources; (5) impact of such action upon the operation of the facility; (6) overall financial resources of the covered entity; (7) overall size of the business of a covered entity; (8) the number, type, and location of its facilities; (9) type of operation or operations of the covered entity, including composition, structure, and functions of the workforce of such entity, and (10)geographic separateness, administrative or fiscal relationship of the facility or facilities in question to the covered entity. Garthright-Dietrich v. Atlanta Landmarks, Inc., 452 F. 3d 1269, 1272-73 (11<sup>th</sup> Cir. 2006).
- 18. The obligation to engage in readily achievable barrier removal is a continuing one. Over time, barrier removal that initially was not readily achievable may later be required

because of changed circumstances. DOJ ADA Title III Technical Assistance Manual, Section III-4.4400 Continuing obligation.

- 19. Plaintiff will undoubtedly return to the Subject Premises once the barriers to access have been remediated—not only to avail himself of the goods and services available at the Subject Premises, but to confirm and assure himself that the Subject Premises has been brought into compliance with the ADA and *maintained* in compliance with the ADA so that Plaintiff and other persons with disabilities will have equal access to the Subject Premises without fear of discrimination, endangerment of their safety, or social and public embarrassment.
- 20. Independent of his personal desire to access this place of public accommodation as required by law, Plaintiff is an advocate of the rights of similarly situated persons with disabilities and an advocate for asserting his own civil rights. However, Plaintiff is deterred from returning to the Subject Premises as long as the Defendants continue to operate the Subject Premises in violation of the ADA and ADAAG.
- **21.** Plaintiff has a realistic, credible, and continuing threat of discrimination by the Defendants as long as the Subject Premises remains in non-compliance with the ADA.
- 22. Defendants have discriminated against Plaintiff and others with disabilities by denying access to, and full and equal enjoyment of the goods, services, facilities, privileges, advantages and/or accommodations of the Facility, as prohibited by 42 U.S.C., § 12182, et. seq., and by failing to remove architectural barriers as required by 42 U.S.C., § 12182(b)(2)(A)(iv) and will continue to discriminate against Plaintiff and others with disabilities unless and until Defendants are compelled to remove all physical barriers that exist at the Facility, including those specifically set forth herein, and make the Facility accessible to and usable by persons with disabilities, including Plaintiff.

23. Plaintiff has suffered and continues to suffer direct and indirect injury as a result

of the ADA violations that exist at the Subject Premises and the actions or inactions described

herein.

24. Plaintiff is without adequate remedy at law and is suffering irreparable harm, and

reasonably anticipates that he will continue to suffer irreparable harm unless and until

Defendants are required to remove the physical barriers, dangerous conditions and ADA

violations that exist at the Facility, including those set forth herein.

25. Plaintiff has been obligated to retain undersigned counsel for the filing and

prosecution of this action. The Plaintiff is entitled to have his reasonable attorney's fees, costs

and expenses paid by the Defendants, pursuant to 42 U.S.C., §§ 12205 and 12217.

26. Pursuant to 42 U.S.C. §12188(a), this Court is provided with authority to grant

injunctive relief to Plaintiff, including an order to alter the subject Facility to make it readily

accessible to and useable by individuals with disabilities to the extent required by the ADA, and

closing the subject Facility until the requisite modifications are completed.

WHEREFORE, Plaintiff respectfully requests that the Court issue a permanent

injunction enjoining Defendants from continuing is discriminatory practices, ordering

Defendants to remove the physical barriers to access and alter the subject Facility to make it

readily accessible to and useable by individuals with disabilities to the extent required by the

ADA, closing the subject Facility until the barriers are removed and requisite alterations are

completed, and awarding Plaintiff his reasonable attorney's fees, expert fees, costs and litigation

expenses incurred in this action.

Respectfully submitted,

s/ Glenn R. Goldstein

Glenn R. Goldstein, Esq. (FBN: 55873)

Attorney for Plaintiff
Glenn R. Goldstein & Associates, PLLC
8101 Biscayne Blvd., Ste. 504
Miami, Florida 33138
(561) 573-2106
GGoldstein@G2Legal.net

## s/ Lauren N. Wassenberg

Lauren N. Wassenberg, Esq. (FBN: 34083)

Attorney for Plaintiff

Lauren N. Wassenberg & Associates, P.A.
33 SE 4<sup>th</sup> St., Ste. 100

Boca Raton, FL 33432
(561) 800-0405

WassenbergL@gmail.com